


**Spare parts Micropilot S FMR540**  
Ersatzteile Micropilot S FMR540

07.2007

If the calibration seal is broken, the national calibration authority should normally be informed within 24 hours.  
Bei Bruch des Eich-Siegels muss in der Regel die nationale Eichbehörde innerhalb 24 Stunden informiert werden!



For using in Ex zones cable glands of the generation  $\geq$  B must be required! In addition the permissible temperature range has to be observed ( $> 75^{\circ}\text{C}$ ).