

Version: Doppelkammer/78 mm Hub
 Serviceposition Kammer innen
 Antrieb pneumatisch
 Version: Double chamber/78 mm stroke
 Service position internal chamber
 Actuation pneumatical

CPA875-xxE5xxxxxxxx
 CPA875-xxF5xxxxxxxx

Ersatzteilbestellcode /Spare part odercode
 XPC0001-A+Positionsbezeichnung
 XPC0001-A+position item text

