

Version: Doppelkammer/78 mm Hub
 Serviceposition Frontkammer
 Antrieb pneumatisch
 Version: Double chamber/78 mm stroke
 Service position front chamber
 Actuation pneumatical

CPA875-xxE6xxxxxxxxx
 CPA875-xxF6xxxxxxxxx

Ersatzteilbestellcode /Spare part odercode
 XPC0001-A+Positionsbezeichnung
 XPC0001-A+position item text

