

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

Field Xpert SMT77 1.03.00

New software version is released

1 Type of Product

- ☒ Software/hardware for device configuration/tablet/handheld/device drivers etc.
☐ Modem/interface

Manufacturer : Endress+Hauser Process Solutions AG
Product : **Field Xpert SMT77**
Type and order code : **SMT77**

2 Software

Previous software version : 1.00.00, 1.00.02, 1.01.00, 1.02.00

New software version : **1.03.00**

How can the previous software version number be identified? : Inside the current software version under menu item **? (Help) -> License -> Version**

Description of the modification in comparison with the predecessor version : Main changes to the software are:

- **Automatic DTM Update – monthly DTM packages will be released and automatically downloaded**
- **Upload of HART device reports in our IIoT digital service «Library»**
- **Improvements in usability**

Where to get the new Software?

If there is a valid maintenance period (Software Update Service) of the tablet and an Internet connection is detected, the Field Xpert SMT77 software automatically recognizes a new software version and downloads the software.

The user then can execute the installation or skip it.

If the maintenance period of the tablet has expired, we kindly ask you to contact the Endress+Hauser sales. (Topic: Field Xpert SMT77 Software-Update Contract, Software Update Service)

The communication DTMs und device DTMs and additional the

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

new drivers can be downloaded at the Endress+Hauser software portal:

<https://software-products.endress.com/>

Additionally, we recommend to keep the Microsoft Windows operating system up-to-date.

3 Compatibility

Is the new product software compatible with the previous version?

☒ Yes

☐ No, reason:

Is a software update generally recommended?

☒ Yes, reason:

It is recommended to update to the new software version of the Field Xpert SMT77. This ensures that Field Xpert can operate with newer field devices. Furthermore, the functionality have been extended and found issues have been solved.

☐ No, reason:

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

4 Instruction manual

Is a new instruction manual necessary due to the software modification?

- ☐ Yes
☒ No

The manual that corresponds to the current version is:

Product	Document	Document identifier
Field Xpert SMT77	Operating Instructions (BA)	BA01923S/04/EN/02.18

The instruction manual can be downloaded from the Internet:

<https://www.endress.com/SMT70> -> Tab "Documents / Manuals / Software "

5 Price

Is there a change in price in comparison with the predecessor version?

- ☐ Yes, new list price and update costs
☒ No